

I (MA)

180021100543

Test report

Report No. JJ20190249

Name of the project: pharmaceutical composite film/bag
production workshop, microbiology room

Unit entrusted Chengde Technology Co., Ltd

State Administration of Food and Drug Administration Zhejiang Drug
Packaging Material Inspection Center


Report No. JJ20190249:

Page 1,6 b

Unit entrusted	Chengde Technology C o . , Ltd		
Address	Hong Kong, Cangnan County, Zhejiang Province	Post Office	/
Telephone	18005887679	Spells	/
Name of project	Pharmaceutical film/bag production workshop, microbiology room		
Clean Area	Class 100	2	100 000 24
Level and Quantity	Grade 10,000	8	Level 300,000 /
Location of works	888-1088, Fortune Century Avenue, Longgang, Cangnan County, Zhejiang Province	Project No.	/
Inspection items	Number of air exchange, strong wind speed, static pressure difference, cleanliness, concentration of floating bacteria' Warm waste, relative team photo		
Date of inspection	2019.10.22	Inspection status	Static state
Inspection basis	Methods of testing the clean room () of the pharmaceutical packaging materials production plant of the State Administration of Food and Drug Administration		
Conclusion			
<p>1. Air exchange times: all meet the requirements.</p> <p>2. Section wind speed: all meet the requirements.</p> <p>3. static pressure difference: the pressure difference between clean area and unclean area and between clean area and outdoor meets the requirements.</p> <p>4. cleanliness: all meet the requirements.</p> <p>5, planktonic bacteria concentration: all meet the requirements.</p> <p>6. temperature and relative humidity: all meet the requirements.</p> <p>7. illuminance: all meet the requirements.</p>			

Conclusion: All the comprehensive performance indexes of the project meet the requirements of packaging materials and container management methods for vertical contact drugs.

the specific inspection results are attached.



Signature:

Primary

Date of